

HiEOS 01.0.01 released

2024-01-23 - Christoph Strauss - Switches and Router

This is the first software bugfix release for the HiEOS software for the LRS device family.

Software Release 01.0.01

Bugfixes (see Issue List)

Conteúdo Relacionado

- [HAC_Issue-List_2023-12-13](#)
- [Web-LRS11-01001.zip](#)