

Wissensdatenbank > Produkte > Are Schneider branded Hirschmann products affected by the vulnerability described in CVE-2016-3115?

Are Schneider branded Hirschmann products affected by the vulnerability described in CVE-2016-3115?

- 2024-09-19 - Produkte

Schneider branded Hirschmann products are NOT affected by the vulnerabilities described in CVE-2016-3115.

Only part of the product portfolio is utilizing OpenSSH.

They use the secure default setting of "X11Forwarding=no" as explained in x11fwd.adv.

CVE-2016-3115: <https://nvd.nist.gov/nvd.cfm?cvename=CVE-2016-3115>

x11fwd.adv: <http://www.openssh.com/txt/x11fwd.adv>