

## HiOS 09.0.00 released

2022-01-04 - Christoph Strauss - Switches and Router

Software Release 09.0.00

-----

Bugfixes (see Issue List)

New Functions:

- Responsive GUI
- Profinet Stack update BRS, OS8TX
- Double VLAN Tagging RSP, RSPE, GRS1040, GRS106, MSP40, Octopus2 and Octopus 3

Ähnliche Inhalte

- [Web\\_BRS\\_09000.zip](#)
- [Web\\_DRAGON\\_09000.zip](#)
- [Web\\_GRS\\_09000.zip](#)
- [Web\\_MSP\\_09000.zip](#)
- [Web\\_OCTOPUS\\_09000.zip](#)
- [Web\\_RDD\\_09000.zip](#)
- [Web\\_RSP-2A\\_3S\\_09000.zip](#)
- [Web\\_RSPE\\_09000.zip](#)
- [HAC\\_Issue-List\\_2021-12-21.pdf](#)